




Exterior View from Street



Existing building before remodel



Interior



The existing flat-roofed building had been built with zero setback from the property lines. Due to zoning restrictions, and a desire to conserve materials, the structure was rehabilitated without changing the footprint. Volunteer labor from the church provided demolition down to the steel skeleton. The congregation leases a performing arts center across the street for a sanctuary and parking, while fellowship spaces, offices, and classrooms are all provided within this building. Conferences for up to 300 people can be hosted in the combined assembly room.

